




Transferring measurements by marking centre of hinge arm



Mark hinge arm centre.



Pre-drill (\varnothing 2.5 mm).



Screw on mounting plate.